G

AHERA Six-Month Surveillance Inspection Date: 3/14/23						
Inspector (Print Nam	e): Russell Mealey					
Inspector Signature:						
Location: D-Y Administration Building, 296 Station Ave, S. Yarmouth, Massachusetts						

Location	ACBM	Estimated	VERTEX	March	Comments
	Description	Quantity	April	2023	
			2013	Updated	
			Condition	Condition	
Common Hall	Rock Pattern Sheet Flooring	$50  ext{ ft}^2$	G	G	
Storage # 1	Rock Pattern Sheet Flooring	$50  ext{ ft}^2$	G	G	
Kitchen	Rock Pattern Sheet Flooring	$144  ext{ ft}^2$	G	G	
	12" x 12" Blue Floor Tile and Mastic		G	G	
Men's Room	(Contaminated)	$144  ext{ ft}^2$			

 $144 ext{ ft}^2$ 

Notes:

Women's Room

 $\begin{array}{lll} & ft^2 = Square \ Foot & Cond. = Condition & U = Unknown \\ & lf = Linear \ Foot & G = Good & C = Covered \\ & Unit = Each & MD = Minor \ Damage & NF = Not \ Found \end{array}$ 

12" x 12" Blue Floor Tile and Mastic

(Contaminated)

D = Damaged







G