

AHERA Six-Month Surveillance Inspection Date: 3/14/23

Inspector (Print Name): Russell Mealey

Inspector Signature: _____

Dennis-Yarmouth Regional High School, S. Yarmouth Massachusetts

Location	ACBM Description	Estimated Quantity	VERTEX July 2013 Condition	March 2023 Updated Condition
<i>Lower Level</i>				
Former Boat Shop	9"x 9" Gray Floor Tile and Mastic	132 ft ²	MD (6 ft ²)	MD 10ft ²
Room 003	9"x 9" Gray Floor Tile and Mastic	900 ft ²	MD (4 ft ²)	MD 7ft ²
Room 005	9"x 9" Green Floor Tile and Mastic	900 ft ²	MD (10 ft ²)	MD 10ft ²
Room 007	9"x 9" Gray Floor Tile and Mastic	900 ft ²	G	MD 4ft ²
Room 009	9"x 9" Green Floor Tile and Mastic	900 ft ²	G	MD 4ft ²
Room 011	9"x 9" Gray Floor Tile and Mastic	900 ft ²	MD (3 ft ²)	MD 4ft ²
<i>First Floor</i>				
Room 207	12"x 12" Off-White Tan Streak FT and Mastic	1,512 ft ²	G	MD 1ft ²
Room 207(offices)	12"x 12" Off-White Tan Streak FT and Mastic	1,408 ft ²	G	G
Room 205	12"x 12" Off-White Tan Streak FT and Mastic	2,288 ft ²	G	MD 5ft ²
Auditorium/Stage	Stage Curtain (assumed)	1 Unit	G	G
Maintenance Office Computer Room 301	9"x 9" Gray Floor Tile and Mastic	50 ft ²	SD	SD
Room 306B (gym storage)	9"x 9" Green Floor Tile and Mastic	80 ft ²	SD	SD
Room 343 (electric)	9"x 9" Salmon Floor Tile and Mastic	110 ft ²	G	G
Gymnasium Storage #1 (1977)	12"x 12" Off-White Tan Streak FT and Mastic	300 ft ²	MD (4 ft ²)	MD 6ft ²
Gymnasium Storage #2 (1977)	12"x 12" Off-White Tan Streak FT and Mastic	300 ft ²	MD (4 ft ²)	MD 4ft ²
400-Hall (1977)	12"x 12" Gray Red Streak Floor Tile and Mastic	1,680 ft ²	MD (6 ft ²)	Abated
Room 407 (offices)	12"x 12" Off-White Tan Streak FT and Mastic	576 ft ²	MD (4 ft ²)	MD 5ft ²
Room 411	12"x 12" Off-White Tan Streak FT and Mastic	820 ft ²	G	MD 5ft ²
Room 413	12"x 12" Off-White Tan Streak FT and Mastic	820 ft ²	G	G
Room 415	12"x 12" Gray Red Streak Floor Tile and Mastic	820 ft ²	G	G
Room 417	12"x 12" Off-White Tan Streak FT and Mastic	820 ft ²	G	MD 1ft ²
AV Room	12"x 12" Gray Red Streak Floor Tile and Mastic	2,560 ft ²	G	G



AHERA Six-Month Surveillance Inspection Date: 3/14/23

Inspector (Print Name): Russell Mealey

Inspector Signature: _____

Dennis-Yarmouth Regional High School, S. Yarmouth Massachusetts

Location	ACBM Description	Estimated Quantity	VERTEX July 2013 Condition	March 2023 Updated Condition
<i>First Floor (Continued)</i>				
Room 418B	12" x 12" Gray Red Streak Floor Tile and Mastic	448 ft ²	G	G
Room 418C	12" x 12" Gray Red Streak Floor Tile and Mastic	400 ft ²	G	G
<i>Second Floor</i>				
400-500 Elevator	12" x 12" Gray Red Streak Floor Tile and Mastic	36 ft ²	MD (2 ft ²)	MD 3ft ²
500-Hall (1977-Addition)	12" x 12" Gray Red Streak Floor Tile and Mastic	1,240 ft ²	MD (6 ft ²)	MD 6ft ²
Room 519	12"x 12" Off-White Tan Streak FT and Mastic	900 ft ²	G	MD 2ft ²
Room 524	12"x 12" Off-White Tan Streak FT and Mastic	900 ft ²	MD (2 ft ²)	MD 2ft ²
Room 522	12"x 12" Off-White Tan Streak FT and Mastic	900 ft ²	G	MD 1ft ²
Storage Room Across Room 521A	12"x 12" Off-White Tan Streak FT and Mastic	300 ft ²	G	MD 2ft ²
Room 511	9" x 9" Tan Floor Tile and Mastic	200 ft ²	MD (10 ft ²)	MD 12ft ²
Book Storage by Room 505	9" x 9" Tan Floor Tile and Mastic	144 ft ²	G	G
Room 503-Closet	9" x 9" Salmon Floor Tile and Mastic	80 ft ²	G	G
Room 501C-Storage	9" x 9" Tan Floor Tile and Mastic	64 ft ²	G	MD 4ft ²
Room 501B	9" x 9" Salmon Floor Tile and Mastic	64 ft ²	MD (3 ft ²)	MD 3 ft ²
<i>Mechanical Penthouse</i>				
Former Observatory Area	9" x 9" Gray Floor Tile and Mastic	80 ft ²	SD	SD



Notes:

ft² = Square Foot

lf = Linear Foot

Unit = Each

Y= Yes

N = No

Cond. = Condition

G = Good

MD = Minor Damage

SD = Significantly Damaged

U = Unknown

C = Covered

Fri. = Friable

NPI = Not Previously Identified

Notes/Updated Changes:

Green, Tan, Salmon and Gray colored 9" x 9" Floor Tile and Mastic not previously identified was observed during the VERTEX July 2013 inspection.

Gray/Red Streak, Off-White/Green Streak and Off-White Tan Streak colored 12" x 12" Floor Tile and Mastic not previously identified was observed during the VERTEX July 2013 inspection.



Environmental



Construction



Air Quality



Energy