

**AHERA Six-Month Surveillance Inspection Date:** 3/14/23

**Inspector (Print Name):** Russell Mealey

**Inspector Signature:** \_\_\_\_\_

**Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts**

Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i>Upper Level-Original Section</i>				
Front Entrance	2' x 4' Ceiling Tile (Fissure)	1200 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Cloak Room (Room F)	12" x 12" Brown Spec Floor Tile	300 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	300 ft <sup>2</sup>	G	G
Room E (Police and Supply Room)	12" x 12" Gray Spec Floor Tile	418 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	386 ft <sup>2</sup>	32 ft <sup>2</sup> D	MD 8ft <sup>2</sup>
266/267/268 Corridor	2' x 4' Ceiling Tile (Fissure)	1400 ft <sup>2</sup>	MD	MD
	Red Duct Mastic (Above Ceiling) <sup>1</sup>	60 lf	G	G
Room 268 (Social Worker Office)	12" x 12" Brown Spec Floor Tile (Under Carpet)	400 ft <sup>2</sup>	C	C
	Contaminated Carpet	400 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	368 ft <sup>2</sup>	G	G
Room 267	12" x 12" Brown Spec Floor Tile	900 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	368 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 266	12" x 12" Brown Spec Floor Tile	900 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	368 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 224/Server Room	12" x 12" Brown Spec Floor Tile	340 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	340 ft <sup>2</sup>	G	2ft <sup>2</sup> D
Room H (Reception)	2' x 4' Ceiling Tile (Fissure)	354 ft <sup>2</sup>	G	G
Main Office Closet	12" x 12" Brown Spec Floor Tile	354 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	354 ft <sup>2</sup>	4 ft <sup>2</sup> D	G
Room G	12" x 12" Brown Spec Floor Tile (Under Carpet)	310 ft <sup>2</sup>	C	C
	Contaminated Carpet	310 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	310 ft <sup>2</sup>	G	G
Room I (Principal)	2' x 4' Ceiling Tile (Fissure)	280 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Principal Bath	12" x 12" Brown Spec Floor Tile	340 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	340 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U



<b>AHERA Six-Month Surveillance Inspection Date:</b> <u>3/14/23</u>				
<b>Inspector (Print Name):</b> <u>Russell Mealey</u>				
<b>Inspector Signature:</b> _____				
<b>Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts</b>				
Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i>Upper Level-Original Section (Continued)</i>				
Room I-J Hall and Closet	12" x 12" Brown Spec Floor Tile	48 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	48 ft <sup>2</sup>	G	G
Room J (Dean Office) and Closet	2' x 4' Ceiling Tile (Fissure)	280 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room M/K (Guidance Office)	2' x 4' Ceiling Tile (Fissure)	672 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Clinic (Nurse Office)	12" x 12" Brown Spec Floor Tile	636 ft <sup>2</sup>	G	G
	12" x 12" Gray Spec Floor Tile	264 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Copy Room (in Room 273)	2' x 4' Ceiling Tile (Fissure)	144 ft <sup>2</sup>	G	G
Room 273	2' x 4' Ceiling Tile (Fissure)	960 ft <sup>2</sup>	8 ft <sup>2</sup> D	G
	Interior Window Glazing	SU	P	P
	12" x 12" Tan Floor Tile		NF*	NF*
Room 274	2' x 4' Ceiling Tile (Fissure)	960 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
	12" x 12" Tan Floor Tile		NF*	NF*
Room 275	2' x 4' Ceiling Tile (Fissure)	880 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
	12" x 12" Tan Floor Tile		NF*	NF*
Room 276	2' x 4' Ceiling Tile (Fissure)	640 ft <sup>2</sup>	32 ft <sup>2</sup> D	32 ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P
	12" x 12" Tan Floor Tile		NF*	NF*
Main Office Corridor (Reception-Nurse)	2' x 4' Ceiling Tile (Fissure)	1000 ft <sup>2</sup>	8 ft <sup>2</sup> D	G
	Red Duct Mastic (Above Ceiling) <sup>1</sup>	70 lf	G	G
277-279 Corridor	2' x 4' Ceiling Tile (Fissure)	1440 ft <sup>2</sup>	MD	40 ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P
Room 277	12" x 12" Gray Spec Floor Tile	1320 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1320 ft <sup>2</sup>	24 ft <sup>2</sup> D	G
	Interior Window Glazing	SU	P	P



<b>AHERA Six-Month Surveillance Inspection Date:</b> <u>3/14/23</u>				
<b>Inspector (Print Name):</b> <u>Russell Mealey</u>				
<b>Inspector Signature:</b> _____				
<b>Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts</b>				
Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i>Upper Level-Original Section (Continued)</i>				
Room 277 Bathroom	12" x 12" Gray Spec Floor Tile	36 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	36 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Room 277 Hall	12" x 12" Gray Spec Floor Tile	60 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	60 ft <sup>2</sup>	G	G
Room O (Time Out Room by 277)	12" x 12" Gray Spec Floor Tile	144 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	144 ft <sup>2</sup>	G	G
Room 278 (Music Room)	12" x 12" Gray Spec Floor Tile	1750 ft <sup>2</sup>	G	2 ft <sup>2</sup> D
	2' x 4' Ceiling Tile (Fissure)	1718 ft <sup>2</sup>	G	8ft <sup>2</sup> D
	Black Sink Mastic	2 Units	G	G
	Interior Window Glazing	SU	P	P
Room 278 Bathroom	12" x 12" Gray Spec Floor Tile	96 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	96 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
278-279 Connector Room	12" x 12" Gray Spec Floor Tile	240 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	240 ft <sup>2</sup>	G	G
Music Storage Room	12" x 12" Gray Spec Floor Tile	120 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	120 ft <sup>2</sup>	G	G
Room 279 (Music Room)	12" x 12" Gray Spec Floor Tile	1460 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1460 ft <sup>2</sup>	G	24ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P
Room 217 (Art)	12" x 12" Brown Spec Floor Tile	1280 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1280 ft <sup>2</sup>	16 ft <sup>2</sup> D	G
	Black Sink Mastic	2	G	G
	Interior Window Glazing	SU	P	P
Room 218 (Art)	12" x 12" Brown Spec Floor Tile	1280 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1280 ft <sup>2</sup>	G	G
	Black Sink Mastic	2	G	G
	Interior Window Glazing	SU	P	P
Teachers Lounge	2' x 4' Ceiling Tile (Fissure)	960 ft <sup>2</sup>	16 ft <sup>2</sup> D	G
	Interior Window Glazing	SU	P	P



**AHERA Six-Month Surveillance Inspection Date:** 3/14/23

**Inspector (Print Name):** Russell Mealey

**Inspector Signature:** \_\_\_\_\_

**Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts**

Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i>Upper Level-Original Section (Continued)</i>				
Teachers-Mens Room	12" x 12" Brown Spec Floor Tile	64 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	48 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Teachers-Womens Room	12" x 12" Brown Spec Floor Tile	56 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	48 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Janitor Closet by Boys and Girls Room	12" x 12" Brown Spec Floor Tile	48 ft <sup>2</sup>	8 ft <sup>2</sup> D	8 ft <sup>2</sup> D
	2' x 4' Ceiling Tile (Fissure)	48 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Girls Room by 208	2' x 4' Ceiling Tile (Fissure)	192 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Room 212	12" x 12" Gray Spec Floor Tile	420 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	420 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 210	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	24 ft <sup>2</sup> D	24 ft <sup>2</sup> D
	2' x 4' Ceiling Tile (Fissure)	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 209	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	G	1 ft <sup>2</sup> D
	2' x 4' Ceiling Tile (Fissure)	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 206	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 205	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 204 (Science)	12" x 12" Brown Spec Floor Tile	1010 ft <sup>2</sup>	G	10 ft <sup>2</sup> D
	2' x 4' Ceiling Tile (Fissure)	1010 ft <sup>2</sup>	G	24ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P
	Fixed Laboratory Bench Tops	150 ft <sup>2</sup>	G	G
	Fire Blanket (Assumed)	1 Unit	G	G



**AHERA Six-Month Surveillance Inspection Date:** 3/14/23

**Inspector (Print Name):** Russell Mealey

**Inspector Signature:** \_\_\_\_\_

**Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts**

Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i>Upper Level-Original Section (Continued)</i>				
Room 203 (Science)	12" x 12" Brown Spec Floor Tile	1234 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1208 ft <sup>2</sup>	64 ft <sup>2</sup> D	G
	Interior Window Glazing	SU	P	P
	Fixed Laboratory Bench Tops	300 ft <sup>2</sup>	G	G
	Fume Hood (Assumed)	1 Unit	G	G
Room 202/201	12" x 12" Brown Spec Floor Tile	1010 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1010 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
	Fire Blanket (Assumed)	1 Unit	G	G
201-212 Corridor	2' x 4' Ceiling Tile (Fissure)	3204 ft <sup>2</sup>	40 ft <sup>2</sup> D	8 ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Boys Locker Room	12" x 12" Brown Spec Floor Tile	60 ft <sup>2</sup>	G	G
	12" x 12" Gray Spec Floor Tile	1080 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	60 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Dot)*	954 ft <sup>2</sup>	G	G
	Drywall/Joint Compound	270 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Boys Locker Room Office and Closet	12" x 12" Gray Spec Floor Tile	160 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	152 ft <sup>2</sup>	G	G
Boys Locker Room Office Bathroom	12" x 12" Gray Spec Floor Tile	42 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Dot)*	42 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Boys Locker Room Bathroom	12" x 12" Gray Spec Floor Tile	120 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	136 ft <sup>2</sup>	8 ft <sup>2</sup> D	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Boys Locker Room Shower Room	2' x 4' Ceiling Tile (Dot)*	450 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Stair # 1 to Archive (Former Girls Locker Room)	2' x 4' Ceiling Tile (Fissure)	252 ft <sup>2</sup>	G	G



Environmental



Construction



Air Quality



Energy

<b>AHERA Six-Month Surveillance Inspection Date:</b> <u>3/14/23</u>				
<b>Inspector (Print Name):</b> <u>Russell Mealey</u>				
<b>Inspector Signature:</b> _____				
<b>Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts</b>				
<b>Location</b>	<b>ACBM Description</b>	<b>Estimated Quantity</b>	<b>VERTEX April 2013 Condition</b>	<b>March 2023 Updated Condition</b>
<i>Upper Level-Original Section (Continued)</i>				
Archive (Former Girls Locker Room)	2' x 4' Ceiling Tile (Fissure)	16 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Dot)*	1584 ft <sup>2</sup>	G	D 16ft <sup>2</sup>
	Pipe Fitting Insulation (In Wall Chase Opening)	21 Units	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Archive Storage A	12" x 12" Gray Spec Floor Tile	140 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	140 ft <sup>2</sup>	G	G
Archive Storage B	2' x 4' Ceiling Tile (Fissure)	180 ft <sup>2</sup>	G	2ft <sup>2</sup> D
Archive Storage C, Bathroom and Closet	12" x 12" Gray Spec Floor Tile	200 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	140 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Dot)*	60 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Archive Bathroom	12" x 12" Gray Spec Floor Tile	100 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	100 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Janitor Closet in Stair Adjacent to Archive	12" x 12" Gray Spec Floor Tile	36 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	36 ft <sup>2</sup>	G	G
Storage Closet in Stair Adjacent to Archive	12" x 12" Gray Spec Floor Tile	224 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	216 ft <sup>2</sup>	8 ft <sup>2</sup> D	8 ft <sup>2</sup> D
Stair # 2 to Archive (Former Girls Locker Room)			G	G
	2' x 4' Ceiling Tile (Fissure)	252 ft <sup>2</sup>		
Gym Storage	12" x 12" Gray Spec Floor Tile	384 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	384 ft <sup>2</sup>	144 ft <sup>2</sup> D	G
	Pipe Fitting Insulation	21 Units	G	G
Gym	Flexible Duct Connector Cloth	2 Units	G	G
Auditorium	2' x 4' Ceiling Tile (Fissure)	5300 ft <sup>2</sup>	G	Abated
Stage Room # 2 (By Auditorium Lobby)	12" x 12" Gray Spec Floor Tile	1080 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1080 ft <sup>2</sup>	G	G
	Flexible Duct Connector Cloth	2 Units	G	G



**AHERA Six-Month Surveillance Inspection Date:** 3/14/23

**Inspector (Print Name):** Russell Mealey

**Inspector Signature:** \_\_\_\_\_

**Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts**

Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i>Upper Level-Original Section (Continued)</i>				
Stage	Wood Flooring Paper (Assumed)	1400 ft <sup>2</sup>	C	C
	2' x 4' Ceiling Tile (Fissure)	1400 ft <sup>2</sup>	G	Abated
	Stage Curtains (Assumed)		G	G
Stage Room # 1 (By Main Entrance Lobby)	12" x 12" Gray and Brown Spec Floor Tile	750 ft <sup>2</sup>	G	G
Auditorium/Cafeteria/Gym Corridor	2' x 4' Ceiling Tile (Fissure)	736 ft <sup>2</sup>	G	G
Cafeteria	12" x 12" Brown Spec Floor Tile	3800 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Kitchen Locker Area and Bathroom	12" x 12" Gray Spec Floor Tile	100 ft <sup>2</sup>	G	G
	12" x 12" Brown Spec Floor Tile	48 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	150 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Kitchen Pantry	2' x 4' Ceiling Tile (Fissure)	80 ft <sup>2</sup>	G	G
Cafeteria/Gym Storage Closet	12" x 12" Gray Spec Floor Tile	200 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	200 ft <sup>2</sup>	8 ft <sup>2</sup> D	8 ft <sup>2</sup> D
Cafeteria/Gym Storage Closet	2' x 4' Ceiling Tile (Fissure)	40 ft <sup>2</sup>	G	4ft <sup>2</sup> D
Former Girls Room by 103	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Girls Locker Room	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Girls Locker Room Storage Closet	2' x 4' Ceiling Tile (Fissure)	4 ft <sup>2</sup>	G	G
<i>Lower Level-Original Section</i>				
201-101 Stair	2' x 4' Ceiling Tile (Fissure)	280 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 102	12" x 12" Brown Spec Floor Tile	880 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 103	12" x 12" Brown Spec Floor Tile	900 ft <sup>2</sup>	G	2 ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P
Room 104	12" x 12" Gray Spec Floor Tile	890 ft <sup>2</sup>	G	4 ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P



Environmental



Construction



Air Quality



Energy



**AHERA Six-Month Surveillance Inspection Date:** 3/14/23

**Inspector (Print Name):** Russell Mealey

**Inspector Signature:** \_\_\_\_\_

**Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts**

Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i>Lower Level-Original Section (Continued)</i>				
Room 105	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 106	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 107	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	G	10 ft <sup>2</sup> D
	Interior Window Glazing	SU	P	P
206-107 Stair	2' x 4' Ceiling Tile (Fissure)	280 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 109	12" x 12" Gray Spec Floor Tile	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 110	12" x 12" Brown Spec Floor Tile	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 111	12" x 12" Brown Spec Floor Tile	900 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
210-111 Stair	2' x 4' Ceiling Tile (Fissure)	280 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Room 113	12" x 12" Brown Spec Floor Tile	224 ft <sup>2</sup>	G	G
Womens Room by 113	2' x 4' Ceiling Tile (Fissure)	136 ft <sup>2</sup>	G	8 ft <sup>2</sup> D
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Mens Room by 113	2' x 4' Ceiling Tile (Fissure)	8 ft <sup>2</sup>	G	G
	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Room 115	12" x 12" Brown Spec Floor Tile	1200 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	1192 ft <sup>2</sup>	G	G
	Interior Window Glazing	SU	P	P
Electrical Room adjacent to Room 115	12" x 12" Gray Spec Floor Tile	120 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	120 ft <sup>2</sup>	16 ft <sup>2</sup> D	G
Room 116/115 Connector Room	12" x 12" Gray Spec Floor Tile	170 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	130 ft <sup>2</sup>	24 ft <sup>2</sup> D	G
Room 117	Interior Window Glazing	SU	P	P
Library Offices # 1, 2 and 3	12" x 12" Gray Spec Floor Tile	544 ft <sup>2</sup>	G	G





<b>AHERA Six-Month Surveillance Inspection Date: <u>3/14/23</u></b>				
<b>Inspector (Print Name): <u>Russell Mealey</u></b>				
<b>Inspector Signature: _____</b>				
<b>Nathaniel Wixon Middle School - 901 Route 134, South Dennis, Massachusetts</b>				
Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2023 Updated Condition
<i><b>Addition Section</b></i>				
Library	12" x 12" Gray Spec Floor Tile (Under Carpet)	3360 ft <sup>2</sup>	G	G
	Contaminated Carpet		G	G
Library Storage	12" x 12" Gray Spec Floor Tile	460 ft <sup>2</sup>	G	G
	2' x 4' Ceiling Tile (Fissure)	460 ft <sup>2</sup>	U	G
Boys Room by Room 109	Pipe Fitting Insulation (Assumed Behind Wall)		U	U
Girls Room by Room 107	Pipe Fitting Insulation (Assumed Behind Wall)		G	G
Storage 135	12" x 12" Gray Spec Floor Tile	460 ft <sup>2</sup>	G	G
<i><b>Addition Section</b></i>				
Room 140	Black Sink Mastic**	1 Unit	G	G
Room 141	Black Sink Mastic**	1 Unit	G	G
Room 142	Black Sink Mastic**	1 Unit	G	G
Room 143	Black Sink Mastic**	1 Unit	G	G
Room 144	Black Sink Mastic**	1 Unit	G	G
Room 146	Black Sink Mastic**	1 Unit	G	G
Room 315	Black Sink Mastic**	1 Unit	G	G
Room 316	Black Sink Mastic**	1 Unit	G	G
Room 317	Black Sink Mastic**	1 Unit	G	G
Room 318	Black Sink Mastic**	1 Unit	G	G
Room 319	Black Sink Mastic**	1 Unit	G	G
Room 320	Black Sink Mastic**	1 Unit	G	G
Room 321	Black Sink Mastic**	1 Unit	G	G
Room 314	Black Sink Mastic**	1 Unit	G	G
Loading Dock	2' x 4' Ceiling Tile (Fissure)	16 ft <sup>2</sup>	G	1ft <sup>2</sup>

Notes:

ft<sup>2</sup> = Square Foot  
lf = Linear Foot  
Unit = Each  
Y = Yes  
N = No

Cond. = Condition  
G = Good  
MD = Minor Damage  
D = Damaged  
Fri. = Friable

U = Unknown  
C = Covered  
NF = Not Found  
NPI = Not Previously Identified  
SU = Store Front Window Units



Environmental



Construction



Air Quality



Energy