

**AHERA Six-Month Surveillance Inspection Date:** 3/7/22

**Inspector (Print Name):** Russell Mealey

**Inspector Signature:** \_\_\_\_\_

**Location: D-Y Administration Building, 296 Station Ave, S. Yarmouth, Massachusetts**

Location	ACBM Description	Estimated Quantity	VERTEX April 2013 Condition	March 2022 Updated Condition	Comments
Common Hall	Rock Pattern Sheet Flooring	50 ft <sup>2</sup>	G	G	
Storage # 1	Rock Pattern Sheet Flooring	50 ft <sup>2</sup>	G	G	
Kitchen	Rock Pattern Sheet Flooring	144 ft <sup>2</sup>	G	G	
Men's Room	12" x 12" Blue Floor Tile and Mastic (Contaminated)	144 ft <sup>2</sup>	G	G	
Women's Room	12" x 12" Blue Floor Tile and Mastic (Contaminated)	144 ft <sup>2</sup>	G	G	

Notes:

ft<sup>2</sup> = Square Foot  
lf = Linear Foot  
Unit = Each

Cond. = Condition  
G = Good  
MD = Minor Damage  
D = Damaged

U = Unknown  
C = Covered  
NF = Not Found



Environmental



Construction



Air Quality



Energy